

Due to the complexity of this board, performing component level field repairs is not recommended. If service is required, complete board replacement is required.
For part number information refer to the Exploded View section of this manual.

SONY



